



The Toro Company Controller Repair Board Exchange Fax Order Form

P.O.

Date

Ship to Number	1000036
Distributor name	PRO TURF PRODUCTS - SAN ANTONIO
Ship Address	5026 SERVICE CENTER DRIVE SAN ANTONIO, TX 78218
Phone	210 666-0808 FAX 210 666-0171
Contact	ROB MOHEDANO

Distributor Number	140
Distributor name	PROFESSIONAL TURF PRODUCTS, LP
Bill Address	1010 N. INDUSTRIAL BLVD EULES, TX 76039
Phone	817 785-1900 Fax

Product Line	Part Number	Description	PTP Cost	PTP SELLING	QTY Non Warranty	Comments
Network 8000	R91-1280	All Timing Mechanisms		\$388.00		
	R35-6166	Power Supply		\$246..67		
	R35-6326	Pump Module		\$133.33		
	R35-8502	Valve Board		\$178.33		
	R35-7899	Surge Board		\$201.67		
	R89-8100	Triac Board		\$68.33		
VT3	R35-1077	Timing Mechanism		\$476.67		
VT4	R35-6220	Timing Mechanism		\$416.67		
OSMAC	RNLN3485	Decoder Board		\$416.67		
	RNLN3491A	Triac Board		\$255.00		
E-Series	R102-0187	Narrow Band E-Osmac Decoder		\$385.00		
	R102-2012	Narrow Band RDR Decoder		\$391.67		
	R89-9449-PF	Wide Band Decoder (People Finder)		\$198.33		
	R89-9449-BS	Wide Band Decoder (Base Station)		\$220.00		
	R102-0320	Pump & Common PCB		\$101.67		
	R102-0319	8-Output Module PCB	Order R102-2549			
E-SERIES&VP SAT	R102-2549	8-Output Module PCB (102-8242 LEAD FREE)		\$98.33		
	R102-0318	Output Distribution PCB		\$138.33		
	R102-0181	Surge Ptotection BLK PCB		\$118.33		
	R89-9802	Surge Protection No Switch		\$118.33		
	R89-9803	Surge Protection With Switch		\$118.33		
	R89-9804	Surge Protection W/SW &Gas Pills		\$160.00		
	R89-9896	Earth Group PCB (102-8393 LEAD FREE)		\$60.00		
	R89-9894	24 VAC BAR PCB (102-8392 LEAD FREE)		\$60.00		
Network LTC 1.1	R91-0537	Timing Mech. with Terminal		\$481.67		
	R91-1593	Timing Mech. without Terminal		\$481.67		
	R91-1303	Surge Board		\$231.67		
	R91-1305	Surge Board		\$125.00		
	R91-1307	Sp. Comm		\$106.67		
Network LTC 2.0	R89-7169	Timing Mechanism		\$326.67		
	R89-6977	Back Plane		\$155.00		
	R89-7170	Output Module		\$56.67		
	R89-7171	Pump Common Module		\$61.67		
Network LTC Plus 3.0	R89-8735	Surge Board (Switches Only)	Order R89-8521			
	R89-8736	Surge Board (Surge Only)	Order R89-8521			
	R89-8521	Surge Board (Surge & Switch)		\$176.67		
	R89-8589	Pump & Comm. Surge (102-8086 LEAD FREE)		\$136.67		
Network LTC 4.0	R102-0238	Timing Mechanism		\$353.33		
	R102-0681	8-Output Module (102-8084 LEAD FREE)		\$138.33		
	R102-0682	Pump Common Module (102-8082 LEAD FREE)		\$100.00		
	R102-0612	Distribution Board (102-8078 LEAD FREE)		\$158.33		
Network LTC & Network 8000	R35-8646	Modem Board		\$253.33		
	R89-7519	Standard Modem		\$233.33		
	R102-0104	Standard Modem (102-8568 LEAD FREE)		\$233.33		
	R89-8453	Universal Modem		\$286.67		
	R102-0106	Universal Modem (102-8570 LEAD FREE)		\$286.67		
VP Sat.	R102-3497/ 2.01	Timing Mechanism Version 2.01		\$345.00		
	R102-3497/4.0	Timing Mechanism Version 4.0		\$345.00		
	R102-2782	Power Distribution Board (102-8576 Lead Free)		\$155.00		
	R102-3015	Punp Module (102-8577 LEAD FREE)		\$115.00		
	R102-3125	Radio Adapter (102-8277 LEAD FREE)		\$133.33		
	R102-9124	LTCP/VP Conversion Power Distribution board		\$171.67		
	R363-4638	Maxon Radio Transeiver		\$348.33		
GDC 2 Wired	R102-5044	2 Wire Decoder Mother Board		\$168.33		
Decoder	R102-4339	2 Wire Decoder Daughter Board		\$183.33		
	R102-5918	2 Wire Decoder Stand Alone TM		\$351.67		

Contact: Yolanda Alvarez

Phone: (951) 785-3636

Fax: (951) 785-3635

E-mail yolanda.alvarez@toro.com

*** Please note: Next day request, charges will be according to UPS charges***